

सिंचाई विभाग

शुद्धि पत्र

दिनांक 23 अप्रैल, 2007

क्रमांक 2380/1-एल०.—पडाना-बास लिंक ड्रेन बुर्जी नं० 0 से 49900 अन्तिम छोर तक (बुर्जी नं० 28829/29125 से 49900 तक) जो कि बास बहुउद्देशीय चैनल की बुर्जी नं० 155580 अन्तिम छोर पर गिरती है, के निर्माण हेतु गांव बुआना एवं बुरा डेहर, तहसील जुलाना, जिला जीन्द की भूमि लेनी अपेक्षित है। जिसकी अधिसूचना भूमि अर्जन अधिनियम 1894 की धारा 4 व 6 के उपबन्धों के अन्तर्गत अधीक्षक अभियन्ता, यमुना जल सेवाएं परिमण्डल, जीन्द के क्रमशः पत्र क्रमांक 8068/1-एल०, दिनांक 26 जुलाई, 2006 और पत्र क्रमांक 9314/1-एल०, दिनांक 14 सितम्बर, 2006 द्वारा अधिसूचित की गई थी। जोकि हरियाणा सरकार के राजपत्र में दिनांक 26 जुलाई, 2006 को प्रकाशित हो चुकी है।

उपरोक्त के निरन्तर में निम्नलिखित आयत क्रमांक व किला क्रमांक जिसका वर्णन खाना 7 में है, उस वर्णन को खाना संख्या 6 के वर्णन की बजाय पढ़ा जाये।

विशिष्टि

क्रम संख्या	जिला	तहसील	गांव	हदबस्त नं०	आयत क्र० व किला जो पहले प्रकाशित हो चुका है	आयत क्र० व किला जो प्रकाशित किया जाना है
1	2	3	4	5	6	7
1.	जीन्द	जुलाना	बुआना	19	95/4	95/26

(हस्ता.)...

अधीक्षक अभियन्ता,

यमुना जल सेवाएं परिमण्डल, जीन्द।

IRRIGATION DEPARTMENT

CORRIGENDUM

The 23rd April, 2007

No. 2380/1-L.—The notification under Sections 4 and 6 of the Land Acquisition Act, 1894 for excavation of Padana-Bas Link Drain from RD 0 to 49900 tail (RD 28829/29125 to 49900) outfalling at RD 155580 tail of Bas Multipurpose Channel in Village Buana and Bura Dehar, Tehsil Julana, District Jind for acquisition of land of above noted Villages already published in Haryana Government Gazette, dated 26th July, 2006 issued vide Superintending Engineer, Yamuna Water Services Circle, Jind Notification No. 8068/1-L, dated 26th July, 2006 and No. 9314/1-L, dated 14th September, 2006 respectively.

In continuation of this, following Rectangle/Killa No. mentioned under column No. 7 may be read against Rectangle No. and Killa No. mentioned under column No. 6 :—

Specification

Sr. No.	District	Tehsil	Village	Hadbast No.	Rectangle No./ Killa No. already notified	Rectangle No./ Killa No. to be notified
1	2	3	4	5	6	7
1.	Jind	Julana	Buana	19	95/4	95/26

(Sd.)...

Superintending Engineer,
Yamuna Water Services Circle, Jind.